

# START

## CONVERSATION RECORD

TIME

DATE

19 JAN 93

TYPE

\_\_ VISIT

\_\_ CONFERENCE

X TELEPHONE

\_\_ INCOMING

\_\_ OUTGOING

ROUTING

NAME/SYMBOL

INT

Location of Visit/Conference

NAME OF PERSON(S) CONTACTED  
OR IN CONTACT WITH YOUORGANIZATION (Office,  
dept., bureau, etc.)

TELEPHONE NO.

Randy Spaniel

Kaiser Engineers

509-376-0831


SUBJECT

JA Jones HWSA

### SUMMARY

Randy was involved in the cleanup of the site. He recalled that there was lead contamination. The site had been the location of waste and chemical drums storage. Kaiser used a 988 cat to dig up the site and removed the waste off-site. Randy said that the removal of contaminated soil was limited to how far the 988 cat could safely excavate the soil. After excavation contaminated soil boundary was determined through a visual observation of the soil. No sampling for cleanup verification/confirmation was completed at the time.

On 1 April 1993, Randy said that 220 drums had been removed along with four bulk truckloads of waste going to Northwest EnviroService.



### ACTION REQUIRED

NAME OF PERSON DOCUMENTING  
CONVERSATION  
DEE W. LLOYD

SIGNATURE

*Dee W Lloyd*

DATE

19 JAN 93

### ACTION TAKEN

SIGNATURE

TITLE

DATE